

Ender Club Under Extrusion Workflow

July 2022



Under Extruded with E in mm² ON



**Under Extruded with E in mm² ON
FLOW increased to 250%**

**Almost ideal print
Under Extruded with E in mm² OFF**



Under Extrusion Workflow

8JUL2022



MAKE SURE THIS SETTING IS OFF

